

## Cleaver Tool Replacement Parts

Applied Diamond replaces the cutting edge of cleavers. Extend the life of your tools. Send your cleaver, made by any manufacturer, to Applied Diamond for a cutting edge replacement. We are the industry's foremost cleaver experts and will be able to upgrade your cleaver edge in a cost effective manner.

The popular Fitel beavertail cleaver has a ceramic blade that wears out. Replace it with a more durable diamond part.

**Field Replacement — \$65.00**

**In-house — \$125.00**



Applied Diamond makes replacement diamond parts for the Siecor, Tyco "AMP", Molex and Thomas & Betts cleavers.

**Field Replacement — \$65.00**

**In-house — \$125.00**

Save money on expensive horn assembly replacement. Replace the diamond part within the horn assembly of the York or Ericsson FK-11 and FK-12 cleavers.

**Replacement on Horn — \$165.00**


**Plus Calibration — \$225.00**



Durable tungsten carbide wheels can be provided as replacement parts for Fitel, Fujikura and Furakawa cleavers

**Field Replacement — \$135.00**

**Replacement, Set-up and Testing — \$195.00**



We cost effectively replace the diamond part on your Lucent/OFS TK 7 cleaver.

**Field Replacement — \$190.00**

**Replacement, Set-up and Testing — \$250.00**



♦ 3825 Lancaster Pike ♦ Wilmington, DE 19805 ♦ US: 1-800-222-5143 ♦ DE: 1-302-999-1132

♦ FAX: 1-302-999-8320 ♦ <http://www.usapplieddiamond.com> ♦ Email: [services@usapplieddiamond.com](mailto:services@usapplieddiamond.com)